S Control Chart

The sample standard deviation, like the range, is also an indicator of how much values vary in a sample. While the range reflects the difference between largest and smallest values in a sample, the standard deviation reflects the square root of the average squared distance around the mean of the values. We desire to reduce this variability in our processes so as to produce products as similar to one another as is possible. The S control chart plot the standard deviations of our sample lots and allows us to see the impact of adjustments and improvements in our manufacturing processes.

Examine the boltsize.LAZ data with the S Control Chart. Shown below is the specification form for the analysis and the results obtained:

Sigma Charting		×
Directions: First, click on the variable name that represents the sample lot number. Next, click on the variable that represents the measurement. Click on the optional check box to ob:ain a printout of the chart. Click the Compute button to obtain the results. NOTE! Equal group sizes of 2 to 25 required for Sigma analysis. Control limits are plus and minus 3 sigma. Up to 200 lots may be analyzed.		
Selection Variables: Lot No Bolt Lngth	Group Variable: Lot No	Compute
	Measurement Variable:	Return
	Bolt Lngth	Reset
	Option: Print Chart	Cancel

Figure 1 The SPC S Chart Specification Dialog

```
X Bar Chart Results
Group Size Mean
                 Std.Dev.
  1
     5
          19.88
                    0.37
  2 5
         19.90
                    0.29
          20.16
                    0.27
  3
     5
  4
     5
          20.08
                    0.29
  5
     5
         19.88
                    0.49
  6 5
         19.90
                    0.39
  75
         20.02
                    0.47
  8
    5
         19.98
                    0.43
Grand Mean = 19.97, Std.Dev. = 0.359, Standard Error of Mean =
0.06
Mean Sigma = 0.37
Lower Control Limit = 0.000, Upper Control Limit = 0.779
```



Figure 2 The SPC Sigma Chart